

**Flood Control Project Maintenance  
Levee Inspections****LMA District Cover Sheet****Spring 2013 Levee Inspection Results****Reclamation District No. 0536 Egbert**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2013 Levee Inspection Results**

**Reclamation District No. 0536 Egbert**

Waterway			Bank	Unit Miles
Unit No. 01 Lindsey Slough			Right	5.66
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	04/11/2013 - 04/11/2013			
DWR Inspector	Herman Phillips			
Accompanied By	Page Baldwin RD 536			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 0536 Egbert**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.66	04/11/2013 04/11/2013	Herman Phillips

LMR No.	Levee Mile		Category	Item	Location * + Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End					Start	End	
1				Flood Preparedness & Training	CR M Ma		°	°	38
DWR ID: DWR_RD0536_01_s_2012_38									
2				Operations & Maintenance Manuals	CR M Ma	Inspector Comments: District needs to get a copy of the O&M manual.	°	°	39
DWR ID: DWR_RD0536_01_s_2012_39									
3				Emergency Supplies & Equipment	CR M Ma	Inspector Comments: The district should keep a supply of flood fight materials.	°	°	40
DWR ID: DWR_RD0536_01_s_2012_40									
4	0.00	0.00		Vegetation	LS A Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	38.244947 ° -121.768950 °	38.244947 ° -121.768950 °	43 Y
DWR ID: DWR_RD0536_01_f_2012_43									
5	0.61	1.80		Vegetation	CR M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	38.248952 ° -121.760541 °	38.259810 ° -121.749215 °	9
DWR ID: DWR_RD0536_01_s_2012_9									
6	0.63	1.78		Vegetation	CR M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	38.249064 ° -121.760256 °	38.259617 ° -121.749774 °	3
DWR ID: DWR_RD0536_01_f_2012_3									
7	0.64	0.64		Vegetation	LS M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	38.249170 ° -121.760185 °	38.249170 ° -121.760185 °	6
DWR ID: DWR_RD0536_01_s_2012_6									
8	0.67	0.98	Supplemental	USACE Erosion Survey	WS M Ma	Inspector Comments: 2011 - Multiple sections of slumping bank. 2012: Site is part of the extended inventory, last inspected 2011. [2012 Site ID: LDS_0-6_R]	38.249615 ° -121.760165 °	38.253717 ° -121.757979 °	7
DWR ID: DWR_RD0536_01_s_2013_7									
9	0.74	0.75		Erosion / Bank Caving	LS U Ma	E1 : Note and monitor erosion site.	38.250540 ° -121.759392 °	38.250543 ° -121.759387 °	4 Y
DWR ID: DWR_RD0536_01_s_2012_4									
10	0.93	4.28		Vegetation	WS M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	38.250750 ° -121.749210 °	38.248661 ° -121.717443 °	27
DWR ID: DWR_RD0536_01_s_2012_27									
11	1.10	2.50		Vegetation	CR M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	38.255431 ° -121.757597 °	38.257644 ° -121.738959 °	12
DWR ID: DWR_RD0536_01_s_2013_12									
12	1.27	3.74		Crown Surface / Depressions / Rutting	CR M Ma	C2 : Repair depressions or ruts in the crown or slope.	38.257888 ° -121.757461 °	38.251710 ° -121.726261 °	8
DWR ID: DWR_RD0536_01_f_2012_8									
13	1.55	1.78		Vegetation	WS M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	38.258648 ° -121.753400 °	38.259619 ° -121.749772 °	10
DWR ID: DWR_RD0536_01_f_2012_10									
14	1.72	1.76		Cracking	CR M Ma	CR1 : Monitor and have inspected by geotechnical engineer.	38.259846 ° -121.750813 °	38.259735 ° -121.749959 °	14
DWR ID: DWR_RD0536_01_s_2012_14									

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 0536 Egbert**

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough				Right	5.66	04/11/2013 04/11/2013	Herman Phillips

  

LMR No.	Levee Mile		Category	Item	Location * + Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End					Start	End	
15	1.76	1.76		Repair Gates	CR M Ma	Inspector Comments: This gate needs to be repaired.	38.259822 ° -121.750241 °	38.259822 ° 38.259822 °	33
							DWR ID: DWR_RD0536_01_s_2013_33		
16	1.87	2.35		Vegetation	WS M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	38.259840 ° -121.748343 °	38.258620 ° -121.741373 °	25
							DWR ID: DWR_RD0536_01_s_2013_25		
17	2.18	2.19		Crown Surface / Depressions / Rutting	CR M Ma	C1 : Add appropriate material and re-grade the levee to bring the crown above the design elevation.	38.258019 ° -121.744444 °	38.258093 ° -121.744052 °	23
							DWR ID: DWR_RD0536_01_f_2012_23		
18	2.26	2.26		Trim / Thin Trees	WS M Ma	T1 : Trim trees to at least five feet above ground level.	38.258345 ° -121.742915 °	38.258345 ° -121.742915 °	26
							DWR ID: DWR_RD0536_01_f_2012_26		
19	2.49	2.49		Crown Surface / Depressions / Rutting	CR M Ma	C3 : Add appropriate gravel or road base. Grade and compact.	38.257663 ° -121.739072 °	38.257663 ° -121.739072 °	30
							DWR ID: DWR_RD0536_01_f_2012_30		
20	2.56	2.68		Crown Surface / Depressions / Rutting	CR M Ma	C3 : Add appropriate gravel or road base. Grade and compact.	38.256964 ° -121.738473 °	38.255321 ° -121.738085 °	31
							DWR ID: DWR_RD0536_01_f_2012_31		
21	2.68	3.20		Cracking	CR M Ma	CR1 : Monitor and have inspected by geotechnical engineer.	38.255315 ° -121.738007 °	38.256003 ° -121.729599 °	18
							DWR ID: DWR_RD0536_01_s_2012_18		
22	2.80	5.00		Vegetation	CR U Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	38.255030 ° -121.736028 °	38.245871 ° -121.707596 °	44 Y
							DWR ID: DWR_RD0536_01_s_2013_44		
23	2.85	3.74		Vegetation	LS M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	38.255312 ° -121.735273 °	38.251619 ° -121.726119 °	19
							DWR ID: DWR_RD0536_01_s_2012_19		
24	3.38	3.77		Vegetation	WS U Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	38.252640 ° -121.726552 °	38.251332 ° -121.725900 °	17 Y
							DWR ID: DWR_RD0536_01_f_2012_17		
25	3.38	3.44		Cracking	CR M Ma	CR1 : Monitor and have inspected by geotechnical engineer.	38.256471 ° -121.726605 °	38.255736 ° -121.726059 °	20
							DWR ID: DWR_RD0536_01_s_2012_20		
26	3.68	3.68		Repair Gates	WS M Ma	Inspector Comments: This gate hasn't been repaired. 11-28-2012.	38.252578 ° -121.726439 °	38.252578 ° -121.726439 °	36 Y
							DWR ID: DWR_RD0536_01_s_2012_36		
27	3.93	4.19		Vegetation	WS M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	38.250728 ° -121.722992 °	38.249578 ° -121.718768 °	32
							DWR ID: DWR_RD0536_01_f_2012_32		

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

# Reclamation District No. 0536 Egbert

DWR ID: DWR RD0536 01 s 2013 11Page 3 of 8

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 0536 Egbert**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.66	04/11/2013 04/11/2013	Herman Phillips

LMR No.	Levee Mile		Category	Item	Location *	Rating ** +	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
39	5.39	5.42		Vegetation	LS	M	V2 : Remove the wild growth other than native grasses from the levee slopes.	38.245602 ° -121.702037 °	38.245628 ° -121.700970 °	5

DWR ID: DWR\_RD0536\_01\_s\_ 2012\_5

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 0536 Egbert**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.66	04/11/2013 04/11/2013	Herman Phillips

Levee Mile Report Line	4
Start Levee Mile	0.00
End Levee Mile	0.00
Location	Land Side
Category	
Item	Vegetation
Looking upstream from levee mile 0.00 unit 1 RD 536. Photo taken 4-12-2013.	
phillips_s_20130520_448.JPG	



Levee Mile Report Line	9
Start Levee Mile	0.74
End Levee Mile	0.75
Location	Land Side
Category	
Item	Erosion / Bank Caving
This erosion was noted in prior inspections during the spring of 2011 and the spring of 2012. Photo taken 11-28-2012. This site hasn't changed, it still looks the same. No new photo was taken 4-12-2013.	
phillips_s_20130325_303.jpg	



Levee Mile Report Line	22
Start Levee Mile	2.80
End Levee Mile	5.00
Location	Crown
Category	
Item	Vegetation
Levee mile 2.80-5.00 crown roadway severely overgrown and weeds on both slopes are taller than 4-foot. Photo taken 4-12-2013.	
phillips_s_20130522_449.JPG	



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 0536 Egbert**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.66	04/11/2013 04/11/2013	Herman Phillips

Levee Mile Report Line	24
Start Levee Mile	3.38
End Levee Mile	3.77
Location	Water Side
Category	
Item	Vegetation

RD 536, wild growth on waterside of levee section, can't see the slope. Photo taken 11-28-2012.

phillips\_s\_20130325\_309.jpg



Levee Mile Report Line	26
Start Levee Mile	3.68
End Levee Mile	3.68
Location	Water Side
Category	
Item	Repair Gates

Repair this gate. Someone could get hurt trying to open and close this gate. 4-24-2012. No new picture was taken, no change to this gate. 4-12-2013.

phillips\_s\_20130325\_313.jpg



Levee Mile Report Line	33
Start Levee Mile	4.94
End Levee Mile	4.96
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey

USACE 2012 Photo #1

phillips\_s\_20130325\_305.jpg



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 0536 Egbert**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.66	04/11/2013 04/11/2013	Herman Phillips

Levee Mile Report Line	33
Start Levee Mile	4.94
End Levee Mile	4.96
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey

USACE 2012 Photo #2

phillips\_s\_20130325\_306.jpg



Levee Mile Report Line	34
Start Levee Mile	4.99
End Levee Mile	5.04
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey

USACE 2012 Photo #1

phillips\_s\_20130325\_307.jpg



Levee Mile Report Line	34
Start Levee Mile	4.99
End Levee Mile	5.04
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey

USACE 2012 Photo #2

phillips\_s\_20130325\_308.jpg



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 0536 Egbert**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Lindsey Slough	Right	5.66	04/11/2013 04/11/2013	Herman Phillips

Levee Mile Report Line	38
Start Levee Mile	5.39
End Levee Mile	5.39
Location	Crown
Category	
Item	Encroachments

This gate at levee mile 5.39 was installed with a CVFPB Permit. Photo taken 4-12-2013. This closure was installed prior to the fall inspection 2012.

phillips\_s\_20130522\_450.JPG



* Location	** Rating	+ Issue Type
LS : Land Side	A : Acceptable	Ma : Maintenance Deficiency
WS : Water Side	M : Minimally Acceptable	Ob : Design & System Obsolescence
CR : Crown	N : Not Inspected/Rated	En : Enforcement
	C : Corrected	
	A/W : Acceptable but Monitor & Maintain	
	U : Unacceptable	

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2013 Levee Inspection Results**

**Reclamation District No. 0536 Egbert**

Waterway			Bank	Unit Miles
Unit No. 02 Yolo Bypass			Right	4.97
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	04/12/2013 - 04/12/2013			
DWR Inspector	Herman Phillips			
Accompanied By	Mr Page Baldwin RD 536			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 0536 Egbert**

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass				Right	4.97	04/12/2013 04/12/2013	Herman Phillips

  

LMR No.	Levee Mile		Category	Item	Location * + Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End					Start	End	
1	0.00	4.91		Vegetation	LS U Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	38.244563 ° -121.697132 °	38.198780 ° -121.709690 °	6 Y
DWR ID: DWR_RD0536_02_s_2012_6									
2	0.01	0.06		Encroachments	LS M Ma	EQ : Equipment	38.244240 ° -121.696830 °	38.243630 ° -121.696470 °	5 Y
DWR ID: DWR_RD0536_02_s_2012_5									
3	0.01	3.61		Vegetation	CR M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	38.244335 ° -121.696994 °	38.196982 ° -121.688350 °	15
DWR ID: DWR_RD0536_02_s_2013_15									
4	0.04	2.09		Crown Surface / Depressions / Rutting	CR M Ma	C2 : Repair depressions or ruts in the crown or slope.	38.243813 ° -121.696933 °	38.214528 ° -121.693788 °	1
DWR ID: DWR_RD0536_02_s_2012_1									
5	0.10	0.76		Vegetation	CR M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	38.243047 ° -121.697008 °	38.233617 ° -121.697980 °	4
DWR ID: DWR_RD0536_02_s_2012_4									
6	0.64	0.64		Encroachments	LS M Ma	PI : Pipe	38.235411 ° -121.697981 °	38.235411 ° -121.697981 °	11
DWR ID: DWR_RD0536_02_s_2012_11									
7	0.77	2.15		Crown Surface / Depressions / Rutting	CR M Ma	C3 : Add appropriate gravel or road base. Grade and compact.	38.233467 ° -121.698007 °	38.214050 ° -121.693725 °	16
DWR ID: DWR_RD0536_02_f_2012_16									
8	1.09	1.15		Crown Surface / Depressions / Rutting	CR M Ma	C2 : Repair depressions or ruts in the crown or slope.	38.228881 ° -121.697754 °	38.227928 ° -121.697621 °	2
DWR ID: DWR_RD0536_02_s_2012_2									
9	2.10	2.98		Vegetation	LS M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	38.214666 ° -121.693969 °	38.203122 ° -121.687179 °	14
DWR ID: DWR_RD0536_02_s_2012_14									
10	2.10	3.06		Vegetation	WS M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	38.214665 ° -121.693969 °	38.202240 ° -121.686573 °	13
DWR ID: DWR_RD0536_02_s_2012_13									
11	2.22	2.98		Crown Surface / Depressions / Rutting	CR U Ma	C1 : Add appropriate material and re-grade the levee to bring the crown above the design elevation. Inspector Comments: With the tall weeds growing on the crown you can't see the surface. 4-12-2013.	38.213004 ° -121.693260 °	38.203083 ° -121.687280 °	18 Y
DWR ID: DWR_RD0536_02_s_2012_18									
12	2.54	4.90		Vegetation	CR M Ma	V1 : Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Crown should be free from grasses. The levee should be an all weather road with gravel and hard surface to drive during winter months.	38.208798 ° -121.691057 °	38.198780 ° -121.709691 °	17
DWR ID: DWR_RD0536_02_f_2012_17									
13	2.56	3.43		Vegetation	LS M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	38.208572 ° -121.690870 °	38.197429 ° -121.683666 °	21
DWR ID: DWR_RD0536_02_s_2013_21									

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 0536 Egbert**

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass				Right	4.97	04/12/2013 04/12/2013	Herman Phillips

  

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
14	2.76	3.31		Vegetation	WS	M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	38.205944 ° -121.689174 °	38.199012 ° -121.684186 °	25
DWR ID: DWR_RD0536_02_s_2013_25										
15	3.43	3.94		Crown Surface / Depressions / Rutting	CR	M Ma	C2 : Repair depressions or ruts in the crown or slope.	38.197248 ° -121.683670 °	38.196687 ° -121.692757 °	22
DWR ID: DWR_RD0536_02_s_2012_22										
16	3.69	3.70		Erosion / Bank Caving	WS	M Ma	E2 : Schedule repair of erosion site prior to the next inspection.	38.196982 ° -121.688350 °	38.196850 ° -121.688542 °	10
DWR ID: DWR_RD0536_02_s_2012_10										
17	3.74	3.75		Crown Surface / Depressions / Rutting	CR	M Ma	C1 : Add appropriate material and re-grade the levee to bring the crown above the design elevation.	38.196881 ° -121.689038 °	38.196871 ° -121.689220 °	3
DWR ID: DWR_RD0536_02_s_2013_3										
18	4.26	4.26		Encroachments	CR	M En	PI : Pipe Inspector Comments: There is no permit for thhis pipework. The owner is the District's President Mr. Page Baldwin.	38.196406 ° -121.698410 °	38.196406 ° -121.698410 °	7 Y
DWR ID: DWR_RD0536_02_s_2013_7										

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 0536 Egbert**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	4.97	04/12/2013 04/12/2013	Herman Phillips

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	4.91
Location	Land Side
Category	
Item	Vegetation

RD 536 Looking downstream from levee mile 0.00. Unsatisfactory wild growth greater than 2-foot on levee section on both slopes and crown roadway. Photo taken 4-12-2013.

phillips\_s\_20130522\_452.JPG



Levee Mile Report Line	2
Start Levee Mile	0.01
End Levee Mile	0.06
Location	Land Side
Category	
Item	Encroachments

Equipment placed on landside easement Unit 2. Photo taken 4-12-2013.

phillips\_s\_20130522\_451.JPG



Levee Mile Report Line	11
Start Levee Mile	2.22
End Levee Mile	2.98
Location	Crown
Category	
Item	Crown Surface / Depressions / Rutting

Looking downstream along levee mile 2.22-2.95 at the crown roadway. Photo taken 4-24-2012. During the spring inspection, 4-12-2013, no maintenance has been done on the levee section. Looks the same.

phillips\_s\_20130228\_169.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 0536 Egbert**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Yolo Bypass	Right	4.97	04/12/2013 04/12/2013	Herman Phillips

Levee Mile Report Line	18
Start Levee Mile	4.26
End Levee Mile	4.26
Location	Crown
Category	
Item	Encroachments

Equipment and diesel pump placed on the water ward slope and shoulder of unit 2. Photo taken 4-12-2013.

phillips\_s\_20130523\_453.JPG



Levee Mile Report Line	18
Start Levee Mile	4.26
End Levee Mile	4.26
Location	Crown
Category	
Item	Encroachments

This is another view of the pipe through levee.

phillips\_s\_20130523\_454.JPG



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---